


Postville 1



- East Williams street
- While the sidewalk narrow, it is well maintained, well light and is scenic

Postville 2



- This is badly damaged sidewalk on Reynolds street
- The hole is quite deep and could potentially cause injury to pedestrians

Postville 3



- This is another part on Reynolds street where the sidewalk is in need of repair

Postville 4



- This is a side walk that is indistinguishable from the parking lot of a local grocery store.
- A handrail to distinguish between the two
-

Postville 5



- This is a portion of sidewalk on Military rd. Next to a local church, it is very well maintained.

Postville 6



- This is further on down Military road where the side walk narrows considerably and is not as well maintained.

Postville 7



- Military Rd.
- This is a pipe sticking out of the sidewalk about 8 inches, this is a tripping hazard to pedestrians

Postville 8



- Military Rd.
- This is an overgrown hedge, a simple way to make walkability easier is simply trimming back hedges.

Postville 9



- This is where the sidewalk ends abruptly on Military Rd.
- A road that is perpendicular to this also does not have significant sidewalk on which pedestrians could walk.

Postville 10




- Maple st.
- There is very little sidewalk, so a pedestrian would simply have to turn around and go the way from which they came.

Postville 11



- Summer St.
- In a cross walk on the street, there is rebar uncovered, and could be a potential tripping hazard.

Postville 12



- South Lawler
- There were many baskets on a wide, well maintained sidewalks, that added to their scenic appeal.